

Test Report No.: SDHL1811026064FT Date: Nov.28, 2018 Page 1 of 4

SISO A/S

MILEPARKEN 11, DK-2740 SKOVLUNDE, DENMARK

The following sample(s) was / were submitted and identified on behalf of the client as:

Sample Description : 11.05.650-0 CABINET HANGER "CLIFF", MALE PART, BLACK PC,

F/CHIPBOARD SCREWS

11.05.651-0 CABINET HANGER "CLIFF", FEMALE PART, BLACK PC,

F/CHIPBOARD SCREWS

Style / Item No. : 11.05.650-0 11.05.651-0

Sample Receiving Date : Nov.15, 2018

Test Performing Date : Nov.15, 2018 to Nov.28, 2018

**Test Result Summary** 

Test(s) Requested	Result(s)
Static load test	250 kg no damage.
Summary:	

1. For further details, please refer to the following page(s).

Signed for and on behalf of Shunde Branch SGS-CSTC Co., Ltd.

Bill Wang

Approved signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.apx">http://www.sgs.com/en/Terms-and-Conditions.apx</a>, and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Condi

| Fi,f<sup>(1</sup>Buiding,European Industrial Parti,No.1 Sturtne South Read, Wustan Section,Dallaring Town,Shurube,Fosharo,Garapdong,Orina 528333 t (86-757)22805888 f (86-757)22805888 www.sgs.group.com.cn 中国・广东・佛山市顕徳区大良街道亦事处五沙順和南路「号欧洲工业园一号厂房首层 邮编:528333 t (86-757)22805888 f (86-757)22805888 e g sgs.china@sgs.com



Test Report No.: SDHL1811026064FT Date: Nov.28, 2018 Page 2 of 4

### **TESTS AND RESULTS**

#### **Test Conducted:**

Static load test according to applicant's requirement.

## No. of Sample:

8 pieces. For more sample information and pictures, please refer to the following page.

Test and Requirements	Test Results
Static load test  Mount four sockets on the wall, the configuration position is 300 mm by 300 mm.  Mount four plugs on one board, the configuration position is also 300 mm by 300mm.  Have the four pairs of sets (socket and plug) engaged.  Apply a vertical force on the center of the upper edge of the board.  Increase the vertical force until the engagement is damaged or 250 kg is reached.  Record the maximum force.	250 kg no damage.

#### Remark:

1. For the sample information and pictures, please refer to the following page.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.aspx">http://www.sgs.com/en/Terms-and-Conditions.aspx</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-a-Document.aspx">http://www.sgs.com/en/Terms-and-Conditions/Terms-a-Document.aspx</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307 1443, or email: CN.Doccheck@sgs.com

1443, or email: CN.Doccheck@sgs.com


1457 \*\*Balton Times whet before Discovery Inspection and the content of the content or appearance or appearance of the content or


| Fi,f<sup>(1</sup>Buiding,European Industrial Parti,No.1 Sturtne South Read, Wustan Section,Dallaring Town,Shurube,Fosharo,Garapdong,Orina 528333 t (86-757)22805888 f (86-757)22805888 www.sgs.group.com.cn 中国・广东・佛山市顕徳区大良街道亦事处五沙順和南路「号欧洲工业园一号厂房首层 邮编:528333 t (86-757)22805888 f (86-757)22805888 e g sgs.china@sgs.com





# Test Report No.: SDHL1811026064FT Date: Nov.28, 2018 Page 3 of 4

# Sample as Received













| 作。| 「Building European Industrial Part Na.1 Sturtne South Read, Wuste Section, Dallaring Town, Shunde, Fisshar, Garapptong, Ohina 528333 t (86-757)22805888 f (86-757)22805888 www.sgs.group.com.cn 中国・广东・佛山市原徳区大良街道办事处五沙原和南路1号欧洲工业园一号厂房首层 邮编:528333 t (86-757)22805888 f (86-757)22805888 e sgs.china@sgs.com



Test Report No.: SDHL1811026064FT Date: Nov.28, 2018 Page 4 of 4







\*\*\*End of Report\*\*\*



| 作。| 「Paiding European Industrial Part Na.1 Struthe South Read、Wuste Section, Dallaring Town, Shunde, Fisshar, Garapdong China 528333 t (86-757)22805888 f (86-757)22805888 www.sgs.group.com.cn 中国・广东・佛山市原徳区大良街道办事处五沙原和南路1号欧洲工业园一号厂房首层 邮编:528333 t (86-757)22805888 f (86-757)22805888 e sgs.china@sgs.com